


Electrical Pressure Is Measured in

A practical guide to electrical pressure is measured in, covering the reader intent, the relationship to electrical pressure is measured in, key evaluation criteria, common risks, and the information the intended project audience should confirm before taking the next step.



Main topic: Main Page
<https://www.level-meters.com/>

In the realm of industrial automation and process control, understanding the fundamental units of physics is essential for the correct selection and installation of instrumentation. One of the most common questions encountered by junior engineers and technicians is how various physical forces are quantified. When discussing the force that drives an electric current through a circuit, we often use the term "electrical pressure." In technical and scientific terms, electrical pressure is measured in volts (V).

This measurement, known as voltage or potential difference, is the cornerstone of electrical engineering. For a manufacturer like Welk, which specializes in level measurement instruments such as radar level meters and ultrasonic sensors, voltage is the primary force that powers the sophisticated electronics required to monitor industrial processes. Understanding how electrical pressure functions is not merely a theoretical exercise; it is a practical necessity for ensuring that instruments operate accurately and safely within a facility's power infrastructure.

| The Principle of Electrical Pressure

To understand why electrical pressure is measured in volts, it is helpful to use the hydraulic analogy, which is particularly relevant in the field of level measurement. In a water system, pressure is the force that pushes water through pipes. This pressure can be generated by a pump or by the weight of water in a tank (hydrostatic pressure).

In an electrical system, voltage acts as the pump. It is the electromotive force (EMF) that pushes electric charges (electrons) through a conductor. The higher the voltage, the greater the "pressure" available to overcome resistance and move current.

| Defining the Volt

By international standard (SI units), one volt is defined as the difference in electric potential between two points of a conducting wire when an electric current of one ampere dissipates one watt of power between those points. Alternatively, it can be expressed as one joule of energy per coulomb of charge ($V = J/C$).

In industrial level measurement, this "pressure" is what allows a Main Page transmitter to send a signal across hundreds of meters of cabling from a storage tank to a central control room. Without sufficient electrical pressure, the signal would degrade, leading to inaccurate readings or total system failure.

| Measurement Principles in Industrial Instrumentation

In the context of level meters, electrical pressure is measured and managed in two primary ways: as a power source and as a signal carrier.

| 1. Power Supply Voltage

Most industrial level sensors require a specific range of voltage to operate. If the electrical pressure is too low, the internal components—such as the microwave oscillator in a radar level meter or the piezoelectric crystal in an ultrasonic sensor—will not function. Common industrial voltages include:

24V DC: The industry standard for loop-powered instruments.

220V AC / 110V AC: Often used for four-wire systems where high power is required for heating elements or high-intensity displays.

2. Signal Voltage

While many modern systems use a 4-20mA current loop (because current is less susceptible to voltage drops over long distances), some systems still utilize voltage-based signals, such as 0-5V or 0-10V. In these cases, the level of the liquid in a tank is converted into a proportional electrical pressure that the PLC (Programmable Logic Controller) interprets as a depth or volume measurement.

Practical Selection Table for Level Meter Power Requirements

When selecting a level measurement solution, matching the instrument’s electrical requirements to your site’s infrastructure is critical. The following table outlines typical electrical pressure requirements for various Welk instruments.

Instrument Type	Typical Operating Voltage	Current Consumption	Common Application
Radar Level Meter	24V DC (18-36V range)	< 22mA (Loop powered)	Chemical tanks, oil storage
Ultrasonic Level Sensor	24V DC or 220V AC	100mA - 200mA	Water treatment, open channels
Hydrostatic Transmitter	12V to 36V DC	4-20mA	Deep wells, pressurized vessels
Magnetic Level Gauge	24V DC (Transmitter)	20mA	High-temperature boilers
Level Switch (Float)	Up to 250V AC/DC	N/A (Contact rating)	Pump control, overflow alarm

Voltage Drop and Installation Considerations

Because electrical pressure is measured in volts, engineers must account for "voltage drop" during installation. This is the decrease in electrical potential as current flows through the resistance of the cabling.

| Calculating Voltage Drop

In long-distance installations—common in large-scale water treatment plants or tank farms—the resistance of the copper wire can significantly reduce the voltage reaching the sensor. The formula for voltage drop is:

$$V_{\text{drop}} = I \times R$$

Where:

I is the current in amperes.

R is the resistance of the wire in ohms.

If a hydrostatic level transmitter requires a minimum of 12V to operate and is powered by a 24V supply, the total voltage drop across the cabling must not exceed 12V. If the cable is several kilometers long, the resistance may become high enough that the "electrical pressure" at the sensor falls below the operational threshold.

| Shielding and Grounding

To maintain an accurate measurement of electrical pressure, industrial cables must be shielded. Electromagnetic interference (EMI) from nearby motors or power lines can induce unwanted voltage onto the signal wires, leading to "noise." Proper grounding ensures that this interference is directed to the earth, protecting the integrity of the measurement.

| Limitations and Common Risks

While voltage is a fundamental tool, it carries inherent risks and limitations in industrial environments.

1. **Overvoltage Surges:** Lightning strikes or power grid fluctuations can cause a sudden spike in electrical pressure. Without surge protection, this can destroy the sensitive circuit boards inside radar or ultrasonic level meters.

2. **Intrinsic Safety:** In hazardous environments (such as oil refineries), high electrical pressure can create sparks. In these areas, "Intrinsically Safe" (IS) barriers are used to limit the voltage and current to levels that cannot ignite explosive atmospheres.

3. **Measurement Error:** In voltage-signal systems (0-10V), any resistance in the wire directly changes the measured voltage at the PLC, leading to an inaccurate level reading. This is why Welk generally recommends 4-20mA current loops for long-distance transmission, as current remains constant throughout the loop regardless of wire resistance.

| Frequently Asked Questions (FAQs)

| Is electrical pressure the same as electrical current?

No. Electrical pressure is measured in volts and represents the potential energy. Electrical current is measured in amperes (amps) and represents the actual flow of electrons. Think of voltage as the pressure in a water pipe and current as the flow rate of the water.

| Why is 24V DC the standard for level meters?

24V DC is considered a "safe" low voltage that reduces the risk of electric shock to personnel while providing enough electrical pressure to power sensors and drive signals through several hundred meters of wire. It is also easily backed up with battery systems.

| Can I use a 12V power supply for a 24V radar level meter?

Generally, no. Most industrial radar level meters require a minimum of 18V to 24V to power the microwave electronics. If the electrical pressure is insufficient, the device may power on but fail to provide a stable measurement or communicate with the control system.

| How do I measure voltage in a 4-20mA loop?

To check if a level transmitter is receiving enough electrical pressure, you can use a digital multimeter set to DC Volts. Measure across the positive and negative terminals at the instrument. For a standard 24V system, you should typically see between 18V and 24V depending on the load and cable length.

| Conclusion

Understanding that electrical pressure is measured in volts is the first step in mastering industrial instrumentation. Whether you are installing a hydrostatic transmitter in a deep well or a high-frequency radar meter in a chemical reactor, the management of voltage is critical to system reliability. By ensuring correct power supply levels, accounting for voltage drops, and protecting against surges, you can maximize the lifespan and accuracy of your measurement assets.

For engineers seeking reliable, accurate, and cost-effective level measurement solutions, it is vital to pair high-quality instrumentation with sound electrical practices. To explore our full range of radar, ultrasonic, and hydrostatic sensors designed for diverse industrial environments, please visit our [Main Page](#) for detailed technical specifications and application support.